

# ANNUAL SURVEYS.

12045  
1845

No. 26 Survey held at London Date 12<sup>th</sup> Nov 1845  
on the Boat "Calanurus" Master Whitby  
Tonnage 300 Built at Whitby When built 1833  
By whom built Whitby Owners R. Embleton  
Port belonging to London Destined Voyage London  
If Surveyed Afloat or in Dry Dock in Dowsland Dock

Last Survey, No. 10988 Port of London

Classed 10 A 1  
1843 13 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Top-sides <u>Good</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Good</u>
Waterways <u>Good</u>	Plank and Treennails <u>Good</u>	Anchors No. of <u>Good</u>
Hatchway Coverings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>Good</u>	Windlass <u>Good</u>	Clippers <u>Good</u>

General Observations and Opinion,

as required by the Instructions,

at present bottom stripped Caulked from  
old bottom Sheathing down and Resheathed with  
yellow Metal on felt a new iron breast hook fitted  
Committee Minute 14<sup>th</sup> Nov 1845 in hold, and lower hold  
Character assigned Good with yellow Metal covered for general  
use in efficient Condition & may continue as before  
at present survey and hunters reported  
that limits of the ship is 11 Nov 1845

No. 123 Survey held at London Date 11 Nov 1845  
on the Ship "Hercules" Master Phillips  
Tonnage 300 Built at London When built 1810  
By whom built London Owners Daniell & Son  
Port belonging to London Destined Voyage London  
If Surveyed Afloat or in Dry Dock in Hawks Dock

Last Survey, No. 9361 Port of London

Classed R expunged

The Surveyor is required to state the present Condition of the

Decks <u>New in 1844 Good</u>	Transoms <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Top-sides <u>Good</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Cables <u>Good</u>
Waterways <u>New in 1844</u>	Plank and Treennails <u>Good</u>	Anchors No. of <u>Good</u>
Hatchway Coverings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Good</u>
Breasthooks <u>Good</u>	Windlass <u>Good</u>	Clippers <u>Good</u>

General Observations and Opinion,

as required by the Instructions,

at present bottom stripped Caulked from  
old bottom Sheathing down and Resheathed with  
on felt a new iron breast hook fitted  
Committee Minute 14<sup>th</sup> Nov 1845 in hold, and lower hold  
Character assigned Good with yellow Metal covered for general  
use in efficient Condition & may continue as before  
at present survey and hunters reported  
that limits of the ship is 11 Nov 1845

101620-0077