

# REPORT of SURVEY for REPAIRS.

12 1845

Change of Owners

No. 1117 Survey held at Sidon Date November 1<sup>st</sup> 1845  
 on the Bk. John Wilburn Master E. Peasey  
 Tonnage 417 Built at Sunderland When built 1830  
 By whom built \_\_\_\_\_ Owners J. P. Fisher & Sons  
 Port belonging to Sidon Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 11807 Classed 11A1  
 Port Sidon

REPAIRS Has been in dry dock, bottom examined & caulked above the keel,

Present Condition of the

Decks <u>Yes</u>	Treenails <u>Yes</u>	Windlass and Capstan <u>Yes</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>Yes</u>	Timbers of the Frame <u>sound where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Yes</u>	Sails <u>Withstand</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>1842</u>	Standing & Running Rigging <u>Yes</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, From her general sound & efficient state she appears  
likely to retain her present value

© 2019  


The Amount of Fee.....£ 2 : - : - is received by me,

Certificate (if required) : 10 : -

Committee's Minute 18th Dec 1845

Character assigned 11 A 1

Lloyd's Register  
 Foundation

TON 620-0089