

ANNUAL SURVEYS.

12135

No. 21 Survey held at Sodor Date Decr 13th 1845
 on the Bk. Fortitude Master Christmas
 Tonnage 519 Built at Swedia When built 1852
 By whom built _____ Owners M. Sundell
 Port belonging to Swedia Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock Afloat

No. 21/135

Last Survey, No. 10921 Port of Sodor

Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Has been in the dry dock & bottom examined, and from her high & efficient condition may retain her present class

Committee Minute 19th Decr 1845

Character assigned

12 A 1 LD

W. M. D. L.

No. 303 Survey held at Sodor Date Decr 1845
 on the Bk. Diana Jones Master Pullen
 Tonnage 1222 Built at Switzerland When built 1839
 By whom built _____ Owners Lang & Co
 Port belonging to Shroham Destined Voyage Leith & Home
 If Surveyed Afloat or in Dry Dock Afloat

No. 303

Last Survey, No. 107 Port of Shroham

Classed 7A1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Bottom from the keel was examined in March last and was again condition is confirmed in her present class

Committee Minute 19th Decr 1845

Character assigned

12 A 1 LD

W. M. D. L.

Lloyd's Register Foundation

LON620-0170