

ANNUAL SURVEYS.

12190

No. 343 Survey held at London Date Dec 1845
 on the Bark "Durango" Master
 Tonnage 340 Built at New Brunswick When built 1841
 By whom built 501 Owners Narbotte
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock in Gun Dock

Last Survey, No. 676 Port of LiverpoolClassed 5 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>4 in draped</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, at present docked to search for a leak which
was found - the two upper sheets of 9 metal
which had been over the iron bolts of the lower
deck fastenings have been removed the timber
iron bolts removed and the bottom
seams caulked. 44 metal of bottom
repaired. May remain as Certificate (if required)
 Committee Minute 1845
 Character assigned 5

No. 499 Survey held at London Date Dec 1846
 on the Schooner "Winn" Master Cave
 Tonnage 163 Built at Southampton When built 1830
 By whom built 144 Owners Rupell &
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock on what is called the Ways

Last Survey, No. 1135 Port of LondonClassed * A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stems	Pumps <u>—</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>New Boatwright</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>Suff</u>
Plank sheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>None</u>	Standing & Running Rigging <u>Unfitted</u>
Plank (Bottom) and Counter		

General Observations and Opinion, at present laid aground to Clean the Planks
of bottom and Repair damage to boat
and head from Collision - Repair of
the safe Contingency of Dry Docking
 Committee Minute 1846
 Character assigned 5
* A 1 with asterisk Certificate (if required)