

REPORT of SURVEY for REPAIRS.

No. 389 Survey held at London Date Jan²⁶ to Feb⁷ 1846
 on the "Shulloch Castle" Master E. Stamp
 Tonnage 573 Built at London When built 1827
 By whom built Miss Davidson & Co Owners Miss Davidson & Co
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Afloat in West India Dock

Last Survey, No. 13029 Classed 12 A 1
 Port London Net 45 O 11 No 45

REPAIRS now done, of Damages sustained by Collision with the Ship "Osbert" off the North Foreland in her passage to Bombay on the Starboard side abreast of Fore Chains the following is now viz 30 feet of Stern Strake, 27 feet of Plank sheer, 3 Planks of Topside each 2 feet all of East India Teak, Four Stanchions, 32 feet of Main Rail and Bulwark. Four Channel and part of Chain sweep one Plank of Deck Clamps, and two of Ceiling next it, also a new Carling to Fore Hatchway. Four nonstanching knees and one Staple Standard taken down and re-bolled Caulked above the Wale on this side where necessary also the Deck.

The Fore Mast and lower Riggings belonging to it new.

Part of Cargo below Deck discharged.

Present Condition of the

Decks	Treenails	Windlass and Copstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchor No. of
Sheerstrakes	Ceiling	Cables
Topside	Rudder	Hawsters and Warps
Wales	Copper	Standing & Running Riggings
Plank (Bottom) and Counter		

General Observations and Opinion,

This Ship has been efficiently repaired and is entitled to remain as Class. A 1

The Amount of Fee £ 3 : : is received by me, J. P. Martin

Certificate (if required)

Committee's Minute 20th Feb. 1846

Character assigned

Special on Damage £ 44.0.0

Lloyd's Register Foundation

Lon 620-0306