

ANNUAL SURVEYS.

12294

No. 303 Survey held at London Date February 15 1846
 on the "Darius" Master Mason
 Tonnage 308 Built at —
 By whom built — Owners Codrus & Co
 Port belonging to Dartmouth Destined Voyage —
 If Surveyed Afloat or in Dry Dock Afloat

Recd 24/4/46

Last Survey, No. 1228 Port of London Classed B/H

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan <u>efficient</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>—</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>—</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>—</u>	Sails <u>do</u>
Plank Shears <u>—</u>	Counter <u>—</u>	Cables <u>do</u>
Waterways <u>—</u>	Plank and Tweenails (Outside to the Water's Edge) <u>—</u>	Anchors No. of <u>do</u>
Hatchway Coverings <u>—</u>	Rudder <u>—</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>—</u>	Windlass <u>—</u>	Copper <u>do</u> <u>Good</u>

General Observations and Opinion, as required by the Instructions, She is in an efficient condition and may remain as Clipped

Committee Minute 24th Feb 1846
 Character assigned — — —
Houlman
Angerberg

No. Survey held at London Date Feb 17 1846
 on the "Robert Murray" Master —
 Tonnage 258 Built at — When built 1828
 By whom built — Owners Indley
 Port belonging to London Destined Voyage for sale
 If Surveyed Afloat or in Dry Dock Afloat

11

Last Survey, No. 8722 Port of London Classed Res y H

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good & efficient</u>	Capstan <u>efficient</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>do</u>	Masts, Yards, &c. <u>do</u>
Spirkettling <u>Good</u>	Wales <u>do</u>	Sails <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Cables <u>do</u>
Waterways <u>do</u>	Plank and Tweenails (Outside to the Water's Edge) <u>do</u>	Anchors No. of <u>do</u>
Hatchway Coverings <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Breasthooks <u>do</u>	Windlass <u>do</u>	Copper <u>do</u> <u>1855 in India</u>

General Observations and Opinion, as required by the Instructions, Is in an efficient condition and may remain as Clipped.

Committee Minute 24th Feb 1846
 Character assigned — — —
— — —

Lloyd's Register Foundation

LON 620-0328