

ANNUAL SURVEYS.

12319

No. 4475 Survey held at London Date March 4 1846
 on the Ship "Hedra" Master J. C. Drum
 Tonnage 419 Built at London When built 1846
 By whom built 379 Owners C. Walton
 Port belonging to London Destined Voyage Halifax
 If Surveyed Afloat or in Dry Dock In Dawson's Dry Dock

Rec'd 1/11/46

Last Survey, No. 2577 Port of London Classed 10 A 1
2mo 46

The present Condition of the

Docks <u>good</u>	Treenails	Windlass and Capstan
Waterways <u>do</u>	Breasthooks and Stenson } <u>good</u>	Pumps
Cornings <u>do</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings } <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Plank sheers	Clamps and Shelves <u>do</u>	Anchors No. of <u>and sufficient</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables
Top-sides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps
Wales <u>do</u>	Copper <u>Yellow Metal now new</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>do</u>	upon felt to height of 11 feet (see per Mr. Martin)	

General Observations and Opinion,

The Bottom now sheathed with Yellow Metal upon felt to height of 11 feet. She is entitled to remain as Class "A 1"

Committee Minute 10th March 1846

Character assigned 10 A 1 J. C. Martin

Certificate (if required)

No. 13 Survey held at London Date March 2 1846
 on the Ship "Cambia" Master Smith
 Tonnage 215 Built at London When built 1825
 By whom built 1 Owners Tristram & Co.
 Port belonging to London Destined Voyage Apica
 If Surveyed Afloat or in Dry Dock In Messrs. Curling & Young's Dry Dock

Last Survey, No. 6581 Port of Liverpool Classed 12 A 1
Res. 45. D - 2mo 45

The present Condition of the

Docks <u>good</u>	Treenails	Windlass and Capstan
Waterways <u>do</u>	Breasthooks and Stenson } <u>good when dry</u>	Pumps
Cornings <u>do</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings } <u>do</u>	Keelsons <u>do</u>	Sails <u>and</u>
Plank sheers	Clamps and Shelves <u>do</u>	Anchors No. of <u>sufficient</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables
Top-sides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps
Wales <u>do</u>	Copper <u>Y.M. 45 do</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

Now Dock'd to search for Leaks. a strike of Yellow Metal sheathing now stripped off fore & aft, a lifting off of boards cross, and from sheets in depth off buttons on each side. The Leaks supposed to be found and stopped; also strappings replaced.

Committee Minute 10th March 1846

Character assigned 10 A 1 J. C. Martin

Certificate (if required)

LON 620-0353