

Special *Classing* 12689

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date July 11th 14th 1846
on the Ship "Ellenborough" Master M C Chase
Tonnage 1081 Built at Newcastle When built 1842
By whom built 852 27/94 J & W Smith Owners J & W Smith
Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. _____ Classed _____

Port _____

REPAIRS

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, She has been surveyed for the purpose of
ascertaining if she has foreign Oak plank in
her lower deck Ceiling the planks has been many
times coated with paint I caused them to be

The Amount of Fee £ : : is received by me, Spotted (dubbed)
Certificate (if required) : : and am yet unable to
Committee's Minute _____ 18 _____ pronounce with certainty
Character assigned _____ that they are of foreign
Oak