

REPORT of SURVEY for REPAIRS.

Change of Owners

12802

No. *287* Survey held at *London* Date *26th* *Aug^r* 1846

on the *B. 11th Romeo* Master _____

Tonnage *505* Built at *Greenock* When built *1838*

By whom built *Robert Steele* Owners *J Gilmore*

Port belonging to *London* Destined Voyage _____

If Surveyed Afloat or in Dry Dock *in Limekiln Dock*

Last Survey, No. *11871* Classed *12 A 1*

Port *London*

REPAIRS *at present Sheerstrakes and topsides Caulked and Copper dreged and repaired -*

29 Oct. a new Main Mast and Bowspit has now been furnished & rigging refitted -
J. H. Ritchie

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clapps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Radder	Hawsers and Warps
Wales	Copper <i>45</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This Vessel is in Very efficient Condition and may remain as Classed -
J. H. Ritchie

The Amount of Fee.....£ *3* : - : - is received by me, *J. H. Ritchie*

Certificate (if required) : :

Committee's Minute *11th Sept* 1846

Character assigned *12 A 1*



© 2019

Lloyd's Register Foundation

LON 621-0352