

REPORT of SURVEY for REPAIRS.

Change of Owners

13036

No. *724* Survey held at *London* Date *2 Nov* 184*6*
 on the *Bk Medora* Master *Simpson*
 Tonnage *235* Built at *Bristol* When built *1825*
 By whom built _____ Owners *Shepherd &*
 Port belonging to *London* Destined Voyage *Jamaica*
 If Surveyed Afloat or in Dry Dock *in Curling Young & Co Dock*

Last Survey, No. *12344* Classed *1843 Reg'd A 1*
 Port *London*

REPAIRS *at Present docked to inspect the State of Y Metal*
which was smooth & good - Hull Spars and
rigging generally overhauled

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>Y. M. B. W.</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

Good *Good* *Will found & sufficient*

General Observations and Opinion,

This Vessel appears in sound & efficient Condition and may continue as before

The Amount of Fee.....£ / : : is received by me, *W. H. H. H.*

Certificate (if required) : :

Committee's Minute *22nd Dec 1846*

Character assigned *See 7 A 1*



© 2019

Lloyd's Register Foundation

LON 622-0106