

Change of Owners #13095

REPORT of SURVEY for REPAIRS.

No. 13095 Survey held at London Date Nov 20th & 21st 1846
on the Bk "Elizabeth & Jane" Master
Tonnage 336 Built at Sunderland When built 1829
By whom built _____ Owners Miss^{rs} Denham & Smith
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock In Williams' Son's Slipway
See 2074

Last Survey, No. 10485 Classified 10 *A Ship unmilted
Port London Reported 44 Lost

REPAIRS

Nov^r 19th M^r Ordered for Survey to re-class *A 1

Nov^r 20 Attended and Left notice Card recommending that a portion of the Copper and Wood Sheathing be stripped off at the wrinkled parts to examine Main Bottom, that the Ship be laid upon Blocks to examine the Main Keel, also that a portion of the Ceiling be lifted at the Bilges to examine the state of the Timbers she having been stranded at or near Laurenceton

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

The Owners decline conforming to the above recommendation but state that she is about proceeding home to Sunderland to Repair.

We are of opinion that no character should be assigned till she be properly surveyed and repaired

The Amount of Fee.....£ : : is received by me,

Certificate (if required) : :

Committee's Minute _____ 18

Character assigned _____

Special attendance £2.2.0