

REPORT of SURVEY for REPAIRS.

13289

No. 131 Survey held at London Date March 27th 1847
 on the M. Diamond Master Beckford
 Tonnage 399 Built at New Scotland When built 1833
 By whom built _____ Owners Townsey
 Port belonging to London Destined Voyage Tinian
 If Surveyed Afloat or in Dry Dock afloat & in iron dock

Last Survey, No. 11425 Classed 4. F. 1
 Port London SS. 45 - 2 In

REPAIRS as per suggestion being repaired additional
bolts to knees ~~cutting~~ keelsons tried
keelson caulked fitted and sheathed with broad
ship hull, suggesting generally over hauled

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>do</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Plank sheers <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>38/5 1K</u> <u>do</u>
Sheerstrakes <u>Good</u>	Ceiling <u>Good</u>	Cables <u>do</u>
Topsides <u>Good</u>	Rudder <u>Good</u>	Hawsers and Warps <u>do</u>
Wales <u>Good</u>	Copper <u>th. Wood & felt dry</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>Good</u>		

General Observations and Opinion, Is now in an efficient condition fit
for the conveyance of dry and perishable cargo
and may remain as classed Houston

The Amount of Fee.....£ 2 is received by me, H

Certificate (if required) : :

Committee's Minute 13th April 1847

Character assigned Fit for service

b. Begg

L. D.



© 2019

Lloyd's Register
Foundation

LON 622-0369