

LON622-0407

REPORT of SURVEY for REPAIRS.

Change of Owners

13326

No. 522 Survey held at London Date 21st April 1847
 on the BK "Cleveland" Master Geo Sketton
 Tonnage 386 Built at Whitby When built 1825
 By whom built _____ Owners Marwood & Co
 Port belonging to Whitby Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock in West India Dock & Mitchers Dock

Last Survey, No. 11276Classed * A. 1Port London

REPAIRS

at Present Wales, topsides, & sheer strakes scraped bright the fore hoods of lower sheer strake and upper topside plank shifted on larboard side the yellow metal sheathing stripped off and doubling caulked and bottom sheathed to ballast mark with yellow metal New spurs and carrack bits fitted to windlasses and windloos refitted - Part of Ceiling repaired in hold - New fore mast put in and New Main Rigging furnished -

Present Condition of the

Decks	Treenails	Windlass and Capstan	<u>refitted</u> <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps	—
Comings	Transoms, Pointers, and Crutches	Boats	<u>New Fore mast</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.	<u>Sufficient</u>
Lower Deck Beams & Fastenings	Keelsons	Sails	<u>2 Sails</u>
Planksheers	Clamps and Shelves	Anchor No. of	<u>3 B 1-1</u>
Sheerstrakes	Ceiling	Cables	<u>Sufficient</u>
Topsides	Rudder	Hawsers and Warps	<u>New 8" 15' Warps</u>
Wales	Copper	New Main Rigging	<u>Standing & Running Rigging</u>
Plank (Bottom) and Counter	<u>4 Metal New</u>		
General Observations and Opinion,	<u>applied doubling 1847</u>		

This Vessel appears in efficient Condition and in our opinion fit for the safe conveyance of dry & perishable Cargoes to & from all Ports

The Amount of Fee.....£ 2 : — : is received by me, of the words and
 Certificate (if required) : 10 : — May remain as Copy

Committee's Minute 23rd April 1847Character assigned A. 1 as perSpecial £2 : 2 as per

Lloyd's Register
 Foundation