

REPORT of SURVEY for REPAIRS.

& Charge of Owners

1333

No. 1 Survey held at Sidon Date May 11 1844
 on the Bk Constant Master Hemery
 Tonnage 445 Built at Sunderland When built 1842 Launched December
535 By whom built Hemery Owners Hemery
 Port belonging to Sidon Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Richard House Dock

Last Survey, No. 2150 2293 Classed G A 1

Port Sunderland

REPAIRS Painted from the Yellow Metal to the Gunwale
bottom examined & the rigging stripped & overhauled

Gallery dropped off, and an additional pair of Iron pointers
over the quarters of the Poop

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Sufficient</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is throughout in a very good & efficient state to
retain her present class

W. Woodlett

The Amount of Fee.....£ 2 : — : — is received by me, *W. Woodlett* 28th 1844

Committee's Minute 29 April 1844

Character assigned G A 1



© 2019

Lloyd's Register
Foundation

LON 622-10419