

REPORT of SURVEY for REPAIRS.

13504

No. 116 Survey held at London Date June 12 & 25 184 7
 on the the Victor Master T. Wright
 Tonnage 278 Built at Swansea When built 1840
 By whom built T Owners Crawford
 Port belonging to Trurock Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Youngs Dry Dock

Last Survey, No. 124114 Classed 7-21

Port London

REPAIRS June 1847 Shipped, all new treenailed except at the
 bow and stern 6 pairs of long felloes using copper
 battled, new treenails in the planks of the topsides, all
 new Chan net work and Chain bolts, rudder fastenings
 examined, Caulked from the Keel up over all to the
 Comings, Sheer Red with yellow Melol upon felt,
 has been generally overhauled

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass <u>efficient</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>as when seen</u>	Capstan <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Topsides <u>new treenailed &c.</u>	Pumps <u>do</u>
Spirkettling <u>Good</u>	Wales <u>Good</u>	Masts, Yards, &c. <u>do</u>
Plank Shears <u>do</u>	Counter <u>do</u>	Sails <u>do</u>
Waterways <u>do</u>	Plank and Treenails <u>do</u>	Cables <u>do</u>
Hatchway Comings <u>do</u>	Rudder <u>do</u>	Anchors No. of <u>3815 16 11</u>
Breasthooks <u>do</u>	Copper <u>on felt Keel</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion, This Ship which which had indicated
weakness before has been repaired as above at our
suggestion is now in an efficient condition
and may wear as Clapped

The Amount of Fee.....£ 2 : - : - is received by me, Wm. Lloyd's Register
 Committee's Minute 13th July 1847
 Character assigned Good