

REPORT of SURVEY for REPAIRS.

13820

No. 437 Survey held at London Date Sept 20 1844
 on the By Amphitrite Master Creak
 Tonnage 140 Built at London When built 1820
 By whom built Phillips Owners Phillips
 Port belonging to London Destined Voyage ---
 If Surveyed Afloat or in Dry Dock Dry dock

Last Survey, No. 12665

Classed A.1

Port London

REPAIRS

At the present time, the ceiling from the first fullcock down to the feet taken up, and the Chocks removed and replaced with new, and several filling timbers put in new ceiling and many new beams in the bottom. A new length of sheer stake caulked from the steel up felled and sheathed with yellow metal,

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemon <u>do</u>	Pumps <u>do</u>
Cowings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>up for Good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Plank sheers <u>Good</u>	Clamps and Shells <u>do</u>	Anchors No. of <u>2 B 1/2 1 1/2 do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Thwarts <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Yellow metal fit</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, Is in fair Condition fit for the
conveyance of any perishable Cargos & may
remain as Classed

The Amount of Fee.....£ : 10/- is received by me, J. B. Hatcher

Certificate (if required) : : ---

Committee's Minute 20th Nov 1844

Character assigned ---

Special ---

Lloyd's Register
Foundation

LON623-0451