

REPORT of SURVEY for REPAIRS.

13840

No. 105 Survey held at London Date Sept 17 to Oct 2 1847
 on the Brig "Tone" Master Wittichell
 Tonnage 255 Built at Dundee When built 1843
 By whom built _____ Owners Wittichell R & R Souther
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat in West India Dock & lastly Taverney Dry Dock

Last Survey, No. 11740 Classed 9 A 1
 Port London

REPAIRS done at the present time being totally dismasted by a Hurricane off Madagascar the particulars of Stow & Lost, fully stated in Special Survey Report: The vessel bro't to London fully rigged.

The Yellow Metal Sheathing stripped off and renewed upon paper: hung in Stow and Caulked throughout. Bulwarks repaired.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stewson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelf's	Anchors No. of
Sheersirakes	Ceiling	Cables
Topsides	Rudder	Hammers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Yellow Metal now new upon Paper</u>	

General Observations and Opinion,

This Brig is now in good condition in Hull, 19 May 1847 eligible to remain as Classed A. She is now complete in her Equipment and may have the figure & prefixed tonnage. J. A. Martin

The Amount of Fee £ 1 : - : - is received by me

Certificate (if required) : 10 : -

Committee's Minute 16th Nov 1847

Character assigned

Special or Damage £ 3. 3. -



© 2019

Lloyd's Register Foundation

5200-729 No 7