

REPORT of SURVEY for REPAIRS.

Change of Owners

13873

[Signature]
Recd 20 Nov

697 No. 184 Survey held at London Date 19th Nov 1847
 on the Brig "Arab" Master R Early
 Tonnage 184 Built at Prince Edward Street When built 1841
 By whom built 226 Owners Brenan & Co
 Port belonging to London Destined Voyage Coast Trade
 If Surveyed Afloat or in Dry Dock on Williams Way

Last Survey, No. 989 Classed A. 1
1846 SS. 432

Port Plymouth

REPAIRS at Present 2 hold beams clamped - topsides overhauled
bottom Caulked and grained - wales also Caulked
windlass overhauled

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	<u>Overhauled</u>
Waterways		Breasthooks and Stemson		Pumps	<u>Good</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>Good</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	<u>Sufficient</u>
Lower Deck Beams & Fastenings	} <u>Clamp</u>	Keelsons	} <u>Good</u>	Sails	<u>Good</u>
Planksheers		Clamps and Shelves		Anchors No. of	<u>Good</u>
Sheerstrakes		Ceiling		Cables	<u>Good</u>
Topsides		Rudder		Hawsers and Warps	<u>Good</u>
Wales <u>Caulked</u>	} <u>Good</u>	Copper	<u>Now in</u>	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter					

General Observations and Opinion,

This Vessel appears in efficient Condition and fit to remain as Clamped

[Signature]

The Amount of Fee.....£ 1 : — : — is received by me,

Certificate (if required) : 5 : —

Committee's Minute 30th Nov 1847

Character assigned A 1



© 2019

Lloyd's Register
Foundation
LON 624-0053