

REPORT of SURVEY for REPAIRS.

Change of Owners 13920
[Signature]

No. 254 Survey held at London Date Dec 13. 20th 1847
 on the SS Bolton Master J H Gunn
 Tonnage 541 Built at Liverpool When built 1822
 By whom built — Owners Ingram
 Port belonging to London Destined Voyage Port Adelaide
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 12908 Classed A. 1
 Port London 46

REPAIRS

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	<u>Overhauled</u> Sails <u>do</u>
Plank Sheers <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>4 B.S. 1 1/2</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Good</u> <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, She appears throughout in the most efficient condition fit for the conveyance of dry and perishable cargo to & from all parts of the world and may remain as classed.

The Amount of Fee.....£ 3 : — : is received by me, [Signature]

Certificate (if required) : 10 : —

Committee's Minute 28th Dec 1847

Character assigned Not Steady
Wm Hall Brothers



© 2019

Lloyd's Register
 Foundation

10104-0103