

REPORT of SURVEY for REPAIRS.

13938

No. 15 Survey held at London Date 24 Decr 1848
 on the "Bay" Steam Ship Master Mr Webb
 Tonnage 197 Built at New Brunswick When built 1827
 By whom built _____ Owners Gurland & Co
 Port belonging to London Destined Voyage Coal Trade
 If Surveyed Afloat or in Dry Dock on New Crane Dock

Last Survey, No. 11192

Classed F. 1

Port London

REPAIRS

at present the Rule Act has been complied with and the Ship opened at both bilges and the timbers found sound except four timbers on the Starboard side aft and three on the larboard side aft. The Ceiling has there been removed and three timbers fitted and secured in and secured and a pair of iron rollers fitted over them - a pair of iron Hump rollers also fitted in fore body - The after ends of bottom planks have also been shifted on both sides one transom (the second) has been fixed a new track rail fitted and the upper Courses of bottom have been boottop sheathed with wood in felt - all the bottom having been previously caulked - Rudder bush fitted & bands refitted & fastened

Present Condition of the

Decks <u>Good for Claps</u>	Treenails <u>apparently Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Do</u>	Breasthooks and Stemson <u>Do</u>	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Sufficient</u>
Upper Deck Beams & Fastenings <u>Good for Claps</u>	Timbers of the Frame <u>good for Claps</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>Do</u>	Sails <u>Do</u>
Plank sheers <u>Do</u>	Clamps and Shelves <u>Do</u>	Anchors No. of <u>Do</u>
Sheerstrakes <u>Do</u>	Ceiling <u>Do</u>	Cables <u>Do</u>
Topsides <u>Do</u>	Rudder <u>overhauled & bands refitted</u>	Hawsers and Warps <u>Do</u>
Wales <u>Do</u>	Copper <u>None</u>	Standing & Running Rigging <u>Do</u>
Plank (Bottom) and Counter <u>Upper courses sheathed</u>		

General Observations and Opinion,

This Vessel being fit for the conveyance of Cargoes not in their nature subject to sea damage may remain Classed F. 1 and be marked SS 34th Jan 1849

The Amount of Fee £ 1 : : is received by me, J. H. Ritchie

Certificate (if required) : 5 : -

Committee's Minute 7th Jan 1849

Character assigned F. 1

Special £ 2 2 0



© 2019

Lloyd's Register Foundation

LOM624-0121