

REPORT of SURVEY for REPAIRS.

Change of Owner
14082

No. 105 Survey held at London Date Jan 3^d 1848
 on the Brig "Tone" Master _____
 Tonnage 1255 Built at Sunderland When built 1843
 By whom built 276 Owners Gait
 Port belonging to Matta Destined Voyage _____
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 13045 Classed 9 A1
 Port London

REPAIRS

Present Condition of the

| | | |
|---|--|--|
| Decks <u>Good</u> | Treenails <u>Good</u> | Windlass and Capstan <u>efficient</u> |
| Waterways <u>do</u> | Breasthooks and Stemson <u>do</u> | Pumps <u>do</u> |
| Comings <u>do</u> | Transoms, Pointers, and Crutches <u>do</u> | Boats <u>do</u> |
| Upper Deck Beams & Fastenings <u>seem</u> | Timbers of the Frame <u>do</u> | Masts, Yards, &c. <u>do</u> |
| Lower Deck Beams & Fastenings <u>do</u> | Keelsons <u>do</u> | Sails <u>do</u> |
| Planksheers <u>Good</u> | Clumps and Shelves <u>do</u> | Anchors No. of <u>3 B 15 1 H</u> <u>do</u> |
| Sheerstrakes <u>do</u> | Ceiling <u>do</u> | Cables <u>do</u> |
| Topsides <u>do</u> | Rudder <u>do</u> | Hawsers and Warps <u>do</u> |
| Wales <u>do</u> | Copper <u>47</u> <u>do</u> | Standing & Running Rigging <u>do</u> |
| Plank (Bottom) and Counter <u>do</u> | | |

General Observations and Opinion,

It is in good and efficient condition and may remain as classed,

For today

The Amount of Fee.....£ 1 : — : — is received by me, 11/3/48

Certificate (if required) :

Committee's Minute 3rd March 1848

Character assigned 9 A1

Imp's plics 40



© 2019

Lloyd's Register
Foundation

Lon 624-0269