

REPORT of SURVEY for REPAIRS.

Continuation 14547
 No. 903 on the *M^r Musica* Survey held at *London* Date *1819 Aug 18* 184
 Master *J. Mankman*
 Tonnage *201* Built at *Swansea* When built *1838*
 By whom built *27* Owners *Mabson & Co*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *On the ways*

Last Survey, No. *12444* Port *London* Classed *W A 1*

REPAIRS

present time at present taken down Chocks taken out and replaced tubed deck caulked, yellow metal patched and ship generally overhauled

Had her Surveyed in accordance with the Society Rules Section 54. Scraped bright from the top of her masts and both driven out for inspection found very good.

The upper deck coverings upper deck & Hold beam bolts, the outside planks through which they pass. The plank sheers, waterways, beams, frame timbers, stanchions, bulkheads, transoms, the floors, Redsons planking outside from the copper up the bulwark the frame canvas surface of the outside

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Is in an efficient condition and may be continued 3 years A1 from 1848

The Amount of Fee.....£ 3 : : is received by me, *J. Mankman*

Special..... 3 : 3 : -

Certificate (if required)

Committee's Minute *5th Sept 1848*

Character assigned *Capt A*

