

# ANNUAL SURVEYS.

No. 69 Survey held at London Date Sept 4 1848  
 on the Ship "Conclator" Master Jos. P.  
 Tonnage 576 Built at Shields When built 1841  
 By whom built 642 Owners Ridley  
 Port belonging to London Destined Voyage S.W. & India  
 If Surveyed Afloat or in Dry Dock By Rack & Keel

Last Survey, No. 13501 Port of London Classed PA

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 1 1</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>do</u> When put on <u>1847</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion,

Several new timbers after shifts of Ceiling and after lengths of Stag Keelson new, generally over board is in a good efficient condition, and may remain as Clapped

Committee Minute 8th Sept 1848

Character assigned Special F. 1

Certificate (if required)

No. 329 Survey held at London Date Aug 29 1848  
 on the Ship "Comora" Master Franklin  
 Tonnage 182 Built at South When built 1837  
 By whom built 150 Owners Seale  
 Port belonging to Lynn Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Common use etc

Last Survey, No. 2786 Port of Lundholm Classed PA  
 Cont. 45 3

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>do</u> When put on <u>—</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion,

Seen in efficient condition and may remain as Clapped

Committee Minute 8th Sept 1848

Character assigned Spec 3

© 2019

Lloyd's Register Foundation