

ANNUAL SURVEYS.

No. 110 Survey held at LONDON Date 18 Sept 1848
 on the Bk. "The Ariel" Master See above
 Tonnage 575 Built at Chittagong When built 1842
 By whom built See above Owners See above
 Port belonging to LONDON Destined Voyage See above
 If Surveyed Afloat or in Dry Dock in Messrs Young & Co Dock

Last Survey, No. 1372 Port of LONDON Classed AE. 1

The present Condition of the

Decks	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps <u>See above</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>See above</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings	Keelsons <u>Good</u>	Sails <u>See above</u>
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>See above</u> When put on <u>1847</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, at present docked to inspect the state of the
yellow metal which was smooth & good a new four piece
of iron hullson has been fitted - She appears fit for the
safe conveyance of dry & perishable cargoes to & from
3rd Oct 1848

Committee Minute See above
 Character assigned AE. 1 Clipped & fitted with the strength
See above
 Certificate (if required)

No. 114 Survey held at LONDON Date 18 Sept 1848
 on the Bk. "The Lady Nugent" Master See above
 Tonnage 600 Built at Aden When built Rebuilt 1845
 By whom built See above Owners See above
 Port belonging to LONDON Destined Voyage See above
 If Surveyed Afloat or in Dry Dock in Messrs Young & Co Dock

Last Survey, No. 1364 Port of LONDON Classed 10 A 1

The present Condition of the

Decks <u>Caulked</u> <u>Good</u>	Treenails	Windlass and Capstan
Waterways <u>See above</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>well</u>
Lower Deck Beams & Fastenings	Keelsons <u>Good</u>	Sails <u>found</u>
Planksheers	Clamps and Shells	Anchors No. of <u>and</u>
Sheerstrakes	Ceiling	Cables <u>sufficient</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>See above</u> When put on <u>See above</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, at present bottom stripped of the y metal sheathing
only listing, cut out over hull seams & hooding keels and then Caulked
wood sheathing renewed and caulked with yellow metal - Is
in most efficient condition and may receive a cargo
3rd Oct 1848

Committee Minute See above
 Character assigned 10 A 1 See above
 Certificate (if required)