

# REPORT of SURVEY for REPAIRS.

Condition 14764  
 No. 401 Survey held at London Date 6<sup>th</sup> Nov 1848  
 on the MS "Cleopatra" Master Whitby  
 Tonnage 386 Built at Whitby When built 1825  
 By whom built Whitby Owners Marwood  
 Port belonging to Whitby Destination None is for sale  
 If Surveyed Afloat or in Dry Dock Fitchers Dock

Last Survey, No. 428

Classed 10 A, 1  
C 3

Port Whitby

## REPAIRS

### Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheers/rokes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

### General Observations and Opinion,

This ship has been under special  
 for damage from grounding & from collision and  
 in addition to her damaged state she was found  
 to generally decayed as to be unworthy of

The Amount of Fee.....£..... is received by me.

Certificate (if required)

Committee's Minute 11<sup>th</sup> Dec 1848

Character assigned Unsound Character

Spent £

Signature



© 2019  
 Lloyd's Register  
 Foundation