

REPORT of SURVEY for REPAIRS.

& Change of Owners

No. 73 Survey held at London Date Dec^r 15th 1849
on the ship Malabar Master P. M. Clear
Tonnage 373 Built at Glasgow When built 1833
By whom built _____ Owners Johnson & Co
Port belonging to Belfast Destined Voyage Bombay
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 2368 Continued 1047 Classed 12 4 A 1

Port of Chd

REPAIRS Has been in dry dock

Notice left to have a ~~specimen~~ specimen harrow of Steam Anchor
The above has been supplied

Wm Doxey th I have the figure 1

Present Condition of the

Decks <u>good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>good</u>	Pumps
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B^{rs} & 1 Hedge</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	<u>Copper 4th 1047</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion From her general good appearance and opinion she may retain her present shape

W. M. Doxey

The Amount of Fee.....£ 2 : - - is received by me, W. M. Doxey

Certificate (if required) _____

Committee's Minute 22nd Decr 1849

Character assigned 4 A 1



© 2019

Lloyd's Register Foundation

LON626-0018