

REPORT of SURVEY for REPAIRS.

Change of owners
 No. 82 Survey held at *London* Date *Aug 16th 1849*
 on the *Ship "Hepburn"* Master *Wm. Thomson*
 Tonnage *1114* Built at *Calcutta* When built *1814*
 By whom built _____ Owners *W. Thomson*
 Port belonging to *London* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Afloat*

Last Survey, No. *14310* Port *London* Classed *T. 1*
 REPAIRS *Two per Rule 54-60 in 1848*
present time two new half beams to lower deck new pumps

Bottom *felled and downed 1439 - see previous report*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank-sheers	Clumps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Ship opened for inspection by Government Surveyors is in a sound and efficient condition for the conveyance of dry goods to all parts of the world and may remain as classed

The Amount of Fee.....£ 3 : : is received by me,

Special.....

Certificate (if required)

Committee's Minute *Oct 1849*

Character assigned *See above*