

REPORT of SURVEY for REPAIRS.

No. 377 Survey held at London Date 10th Feb 1849
 on the Ship "Lord Dalhousie" Master Ord
 Tonnage 764 Built at Sunderland When built 1847
 By whom built Giles Owners Harrison
 Port belonging to London Destined Voyage North West Wales
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 3351 Port Sunderland Classed 12 A1

REPAIRS

from damage
 Shipped caulked from the keel up over
 all and sheathed with yellow metal upon felt in upper
 course - Hawse pipes out and refitted cutwater additionally
 fitted new false keel put on

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clumps and Shelves	Anchors No. of <u>3 B 1 S 1 K</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Yellow metal</u> When put on <u>1848</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

*It is in good and efficient condition
 and may remain as classed*

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required) :

Committee's Minute 16th Feb 1849

Character assigned 12 A1



© 2019

Lloyd's Register
Foundation

LON626-0141