

15332

REPORT of SURVEY for REPAIRS.

Change of Owners

No. _____ Survey held at London Date 6 June 1849
on the Dr. Sydford Master _____
Tonnage 313 Built at S Shields When built 1840
By whom built _____ Owners Carter & Co
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock in Carters dock

Last Survey, No. _____ Port _____ Classed 10 A 1

REPAIRS at present docked to inspect the state of the
bottom which was found in good Condition

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>three</u> } <u>well</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>found</u>
Lower Deck Beams & Fastenings	Keelsons	Sails } <u>and</u>
Planksheers	Clamps and Shells	Anchors No. of } <u>sufficient</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>yes</u> When put on <u>1847</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>smooth</u>	

General Observations and Opinion,

This Vessel is in good and efficient Condition
and may remain as Classed

The Amount of Fee.....£ : : is received by me, J H Ritchie

Special..... : :

Certificate (if required) : :

Committee's Minute _____ 18 _____

Character assigned _____



© 2019
Lloyd's Register
Foundation

627-0053