

REPORT of SURVEY for REPAIRS.

15357

No. 577 Survey held at London Date 13th 16th Jan^y 1849
 or the B^{re} Ann Miln Master Geo. Thomas
 Tonnage 463 Built at Dundee When built 1841
 By whom built _____ Owners R Leslie
 Port belonging to Dundee Destined Voyage St Phillip
 If Surveyed Afloat or in Dry Dock in Messrs Youngs Dock

Last Survey, No. 1132 Port Dundee Classed GA1

REPAIRS

at present bottom stripped Caulked and Sheathed
 with Yellow Metal on felt above & paper below
 new lower breast hook of iron & ceiling repaired
 new boarder shipped

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

This Vessel is in efficient Condition
 and may remain as afloat

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 14th Aug^t 1849

Character assigned Good



© 2019

Lloyd's Register
 Foundation

LONG27-0078