

15367

Rec'd 19 Aug

## REPAIRS

The Outside Planking from Yellow Metal Sheathing upwards scraped bright, Yellow Metal Sheathing stripped off the Bottom and renewed upon Felt, the Butts of Bottom additionally fastened with a Copper Spike, Treennails and Iron Bolts driven out at various parts for examination; the Planking and Treennails of Pencil Cedar remarkably sound and good.

The Deck, Coamings, Inside, and Outside Planking, Treennails, Plankstrake, Waterway, Beams, Knees, Breast hooks, Knight heads, Hamsse Timbers, Keel, Keelson, Transoms, Floors, Deck Bolts, and Timbers of the Frame where they may be seen have been examined by us and are in good condition, the Present Condition of the original Form appears to be preserved

## General Observations and Opinion.

This Brigantine has now been examined by us in accordance with Special Survey Rule Sec 54.60 with a view to obtaining the ~~star~~ character at the termination of the present

year, and we are of opinion that she is in  
is received by me, &c.

good condition fit for the safe conveyance  
of my and heritable, personal and from

all parts of the world and to be so

17<sup>th</sup> Augt distinguished

Vol 22 of John Wilkes Booth & Martin

*John H. Johnson*