

REPORT of SURVEY for REPAIRS.

No. 15429 Survey held at London Date Aug 12th 1849
 on the Sch "Myvern" Master Norris
 Tonnage 87 Built at Southampton When built 1828
 By whom built — Owners J. Trickey
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Afloat and upon the ways
WIB len 37

Last Survey, No. 5709 Port Liverpool Classed Ex Ship Mitted
repaired

REPAIRS

At the present time shipped the ceiling taken up from the Keelson to 2 feet above the floor heads, floor head cheeks refitted and after filling timbers put in, new ceiling from the Keelson to above the floor heads, including Bilge stokes of fir properly treenailed and bolted, through both in bilges and in her stoke. This shifting of plank extends about 40 feet of the internal length of the keel, part new upper deck shelf of American elm, with some additional fastenings to beam ends. Several new planks in various parts outside, scraped bright from the copper up, and generally overhauled.

Present Condition of the Caulked and Sheathed with yellow Metal upon Paper

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good left hand</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>"</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>Seam</u>	Timbers of the Frame <u>Good when seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>"</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>2 B 1 S 11</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>"</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>"</u>
Wales <u>do</u>	Copper <u>When put on 1849</u>	Standing & Running Rigging <u>repacked</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

The timbers of frame seen in performing the above repairs proved to be very good. She is now in an efficient condition fit for the conveyance of dry and perishable cargoes and may be classed F. 1

The Amount of Fee.....£ : 10 : is received by me,

Special..... : 3 :

Certificate (if required) : 5 :

Committee's Minute 17th Sept 1849

Character assigned Record repairs



© 2019

Lloyd's Register Foundation

LON627-0153