

ANNUAL SURVEYS.

15573

No. 363 Survey held at London Date Nov 7th 1849
 on the Bk Columbus Master A. Cotton
 Tonnage 467 Built at Whitby When built 1832
 By whom built _____ Owners J. Fletcher
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 14713 Port of London 1840 Classed E. 1 Asterisk
SS. 47

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>firm & strong</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bower 1 Stm 2 Hedge</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>When put on 1840</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, From damage - nine new plankings, thirty one feet of new plank sheer 30 feet of spunketting upper works caulked & the bottom examined, is in a very efficient condition for the safe conveyance of dry & perishable cargoes to & from all parts of the world and may continue as classed
 Committee Minute 9th Nov 1849
 Character assigned E. 1 asterisk LD

Certificate (if required)

No. 129 Survey held at London Date Nov 7th 1849
 on the Bk Persia Master J. Stevens
 Tonnage 526 Built at Scarbro When built 1830
 By whom built _____ Owners Hindall & Co
 Port belonging to Scarbro Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 14791 Port of London 1840 Classed 12A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bower 1 Stm 2 Hedge</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>When put on 1840</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>good</u>		

General Observations and Opinion, Has been in dry dock, bottom examined, caulked round the brass, and is in all respects in good condition to continue as classed

Committee Minute 9th Nov 1849
 Character assigned 12A1 LD

Certificate (if required)



© 2019

Lloyd's Register Foundation

CON627-0301