

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 16 Survey held at London Date Nov 19 1849
 on the Bk Talima Master J G Ray
 Tonnage 444 Built at Sunderland When built 1849
 By whom built Hay Owners John Hamilton
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Leinchips Dock

Last Survey, No. 4015 Classed 13 A1

Port Sunderland

REPAIRS Hang in shores a 4 inch false keel, bottom caulked & sheathed with yellow metal over felt on the upper course & below over paper,

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan
Waterways <u>//</u>	Breasthooks and Stemson	Pumps
Comings <u>//</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>//</u>	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>//</u>	Keelsons	Sails <u>good</u>
Planksheers <u>//</u>	Clamps and Shelves	Anchors No. of <u>8</u>
Sheerstrakes <u>//</u>	Ceiling	Cables <u>sufficient</u>
Topsides <u>//</u>	Rudder	Hawsers and Warps
Wales <u>//</u>	Copper	Standing & Running Rigging
Plank (Bottom) and Counter <u>//</u>		

General Observations and Opinion, Appears in an efficient state to continue as classed

R. W. Moleton

The Amount of Fee.....£ 2 : — : — is received by me. W

Certificate (if required) — : —

Committee's Minute 7th Decr 1849

Character assigned 13 A1



© 2019

Lloyd's Register Foundation

LON627-0349