

REPORT of SURVEY for REPAIRS.

15724

No. 182 Survey held at London Date 25th Jan^r 1850
 on the "S Thomas Sparks" Master J. Matches
 Tonnage 437 Built at Wokington When built 1840
 By whom built _____ Owners Sparks & Co
 Port belonging to Wokington Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock In Bridge Yard Dry Dock

Last Survey, No. 8423 Port Liverpool Classed 12 A 1

REPAIRS

At the present time of damage sustained by stress of weather in her passage from Calcutta to London, more particulars in Special Report.

Main and Top gallant Bulwarks and Rails, and twenty-two Rough tree Stantions, new Throat Bolts of Hanging and Standard Iron Knees to Deck, and Hold Beams replaced with new, the nuts of Fell's Patent Plates to each range of Beams have up, the Yellow Metal Sheathing from Bilges upwards stripped off and renewed, Caulked from the Bilges upwards including the Deck, Fore and Mizzen masts new.

Not of damage by accident, The remainder of the Yellow Metal Sheathing (from the above) stripped off and renewed.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} good	Breasthooks and Stemson	} good where seen	Pumps	} In good order and sufficient
Comings		Transoms, Pointers, and Gutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} d ^o where seen	Keelsons	} d ^o	Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling	} d ^o	Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper Metal	When put on <u>new</u>	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

This Ship is now in good condition and appears eligible to remain as Classed A 1

The Amount of Fee.....£ 2 : - : - is received by me,

Special..... 4 : 4 : -

Certificate (if required) _____

Committee's Minute 25th Jan^r 1850

Character assigned 12 A 1

Special Fee for Repair & on Damages } £ 4-4-0



© 2019

Lloyd's Register Foundation

LON 628-0023