

# REPORT of SURVEY for REPAIRS.

15734

No. 873 Survey held at London Date Jan 10<sup>th</sup> 1850  
 on the B<sup>c</sup> Athenian Master Taylor  
 Tonnage 513 Built at Sunduland When built 1842  
 By whom built          Owners Toulmin & Co  
 Port belonging to London Destined Voyage Port Phillip  
 If Surveyed Afloat or in Dry Dock In Mess<sup>r</sup> Lindall's Dry Dock

Last Survey, No. 14638 Port London Classed 10 A 1

## REPAIRS

At the present time of damages sustained by striking the ground at Port Phillip and by stress of weather in her homeward passage, more particular, of which are in Special Report. The Yellow Metal Sheathing stripped off and renewed upon Tilt aloft, and Paper below; Ship hung in Shores and Caulked throughout, the fore part of Poop and the after part of Forecastle strengthened by Iron Stays, two new Stantions, and the Bulwark repaired. Chafed Planking of Bottom dabbled over

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Cleutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Yellow Metal	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

*When put on now new*

## General Observations and Opinion,

This Barque is now in good condition eligible to remain as Classed A 1

The Amount of Fee.....£ 3 : - : - is received by me,

Special..... 4 : 4 : -

Certificate (if required) : 10 : -

Committee's Minute 1<sup>st</sup> Feb<sup>y</sup> 1850

Character assigned 10 A 1 year

Special Report 44<sup>th</sup>  
 or Damage



© 2019

Lloyd's Register Foundation

LON 628 - 0033