

REPORT of SURVEY for REPAIRS.

No. 853 Survey held at London Date Feb² 5th 19th 1850
on the Symmetry Master Richardson
Tonnage 2302 Built at Scarbro When built 1823
By whom built London Owners W Tindall
Port belonging to London Destined Voyage Ceylon
If Surveyed Afloat or in Dry Dock In Mess Tindall's Dry Dock

Last Survey, No. 14881 Port London Classed Rest 40.7 Cont 47.2 AE 1
REPAIRS 49

Now done with a view to obtaining the ~~*~~ character in conformity with Rule Sec R^o 34.60. The Outside Planking from Y Metal upwards scraped bright and examined, Hold Ceiling repaired, two whole Transoms below, and three half Transoms abreast of Mast Put new. Wales Caulked of English Oak

The Deck, Coamings, Deck, and Hold Beam Bolts, inside and outside Planking, Treenails, Planks heel, Waterway Beam, Hooks, Knees, Knight heads, Hamse Timbers, Transoms, Keel Keelson Floors and Timbers of the Frame where they may be seen have been examined by us and are in good condition

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Cleutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper Metal When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This Ship has now been Specially Surveyed by us in accordance with Rule Sec R^o 34.60 and we are of opinion that she is in good condition, fit for

The Amount of Fee.....£ 1 : — : — is received by me,
Special..... 3 : 3 : —
Certificate (if required) : 10 : —

Committee's Minute 26th Feb^y 1850

Character assigned AE 1

Special Survey Fee £3-3-0

record repairs

LON 628-0101