

Condition
REPORT of SURVEY for REPAIRS.

No. 1585 Survey held at London Date Nov 18 - 28 1848
on the My Sandwich Master _____
Tonnage _____ Built at _____ When built 1848
By whom built _____ Owners Pearce
Port belonging to Cork Destined Voyage _____
If Surveyed Afloat or in Dry Dock on the Hard at West Greenwich

Last Survey, No. _____ Port _____ Classed A, 1 Ship
REPAIRS on the

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

She appears in a bad Condition in the fore part under the fore castle, there is a defect in the scarp of the Keelson and at one other part, the Ceiling has been insufficiently fastened and the upper She has had not properly

The Amount of Fee.....£ : : is received by me.

Special..... : :

Certificate (if required) : :

Committee's Minute _____ 18

Character assigned _____

Inspected Special £2.2.-

none is not in a Condition to entitle her to her present Class where had been sent to the owner, there is not any intention to repair

Lloyd's Register
Foundation

LN 628-0158