

REPORT of SURVEY for REPAIRS.

15879
See 21 March

No. 158 on the Survey held at London Date March 19 1850
Parshalton Park Master
 Tonnage 441 Built at Southampton When built 1811
 By whom built _____ Owners Garter
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry in Limekiln Slipway

st Survey, No. 15242 Port London Classed F. 1
6 ms 49
 PAIRS

This Ship now "Specially Surveyed" at request of Mr Webb with a view to raise her Class

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Her general condition is such as cannot be recommended to the Committee for a higher Character than she has at present (viz F. 1) without undergoing large Repair which the present Owners are not disposed

The Amount of Fee.....£ : : is received by me, *to do. I am of opinion that she should remain Classed F. 1*

Special..... : :

Certificate (if required) : :

Committee's Minute 27th March 1850

Character assigned F. 1
SP

J. D. Martin
 © 2019
 Lloyd's Register Foundation
 LON 628 - 0182