

# REPORT of SURVEY for REPAIRS.

15882

No. 135 Survey held at London Date Jan<sup>y</sup> 2 to 1850  
 on the Bermundsey Master Daniel Isaac Puddle  
 Tonnage 445 Built at Whitchy When built 1841  
 By whom built \_\_\_\_\_ Owners Wilson & Co  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock In Mess<sup>r</sup> Fletcher's Dry Dock

Last Survey, No. 14490 Port London Classed 10 A 1

## REPAIRS

At the present time, the Yellow Metal and the Wood Sheathing stripped off and renewed from Wale to Keel the latter upon <sup>40</sup> Full Wale Topsides and then Strakes scraped bright, the Bolts in Lower <sup>40</sup> to Shelf and Lodging knees replaced with Yellow Metal, On the Port side a Plank in Round Strake of Wale at after part of Main Chains, 40 feet in 3<sup>d</sup> Strake down of Bottom in Midship, the fourth Strake of Bottom from Fore part of Fore Chains aft, and twelve After Hoods of Bottom in Buttocks and Run new of English Oak. On the Starb<sup>d</sup> side two After Hoods of Wale, ten After Hoods of Bottom, four second Planks from aft of Bottom, two Planks of upper Course in Bottom 40 feet each and two Planks at the Bilge. All Channels off and refitted, all Treennails renewed from Wale to Bilge, a new Main Piece of Rudder, about 100 feet of Hold Ceiling and two Wood Cheeks new, two Iron Cheeks added, Ship hung in Shaws and Caulked throughout.

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good when seen</u>	Pumps
Comings }	Transoms, Pointers, and Crutches }	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings <u>new when seen</u>	Keelsons <u>new</u>	Main Yard new <u>and sufficient</u>
Planksheers	Clamps and Shelves <u>new</u>	Sails
Sheerstrakes <u>new</u>	Ceiling <u>new</u>	Anchors No. of
Topsides <u>new</u>	Rudder <u>new</u>	Cables
Wales <u>new</u>	Copper <u>new</u> When put on <u>new</u>	Hawsers and Warps <u>new</u>
Plank (Bottom) and Counter <u>new</u>		Standing & Running Rigging <u>new</u>

## General Observations and Opinion,

This Vaque now appears to be in good condition eligible to remain as Classed A 1

The Amount of Fee ..... £ 2 : - : - is received by me,

Special ..... 2 : 2 : -

Certificate (if required) : : :

Committee's Minute 26<sup>th</sup> March 1850

Character assigned 10 A 1

Special Fee 2 2 0  
 extra attendance



© 2019

Lloyd's Register  
 Foundation  
 LONG28 - 0185