

REPORT of SURVEY for REPAIRS.

10041

No. 609 Survey held at London Date May 20th 25 1850
 on the 13th Commodore Master Blissell
 Tonnage 203 Built at Newport When built 1835
 By whom built _____ Owners Sa^d Shepherd
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat in the West India Dock

Last Survey, No. 15505 Port London Classed 12 A 1
 Cost 47 4 5ms 49

REPAIRS

At the present time of damage sustained by stress of weather in her passage from Jamaica to London. More particulars in Special Report. Butwarks all new, Planks her on Forecastle repaired, the ship Caulked from Copper upwards to second beam of Deck next the Waterway, and sundry other slight repairs.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors .No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1049</u>	

General Observations and Opinion,

This Paigue is now in good condition and appears eligible to remain as Classed A 1

The Amount of Fee.....£ 1 : — : — is received by me,

Special..... 2 : 2 : —

Certificate (if required) : :

Committee's Minute 31st May 1850

Character assigned 12 A 1

Special Report & } £2-2-0
 on damage



© 2019
 Lloyd's Register
 Foundation
 LON 628-0348