

REPORT of SURVEY for REPAIRS.

126
No. 124
Survey held at Soudon Date 24th June 1850
on the "West Indian" Master Mills
Tonnage 328 Built at Bristol When built 1829
By whom built _____ Owners J Purdie
Port belonging to Soudon Destined Voyage _____
If Surveyed Afloat or in Dry Dock in New Crane Dock

Last Survey, No. 14225 Port Soudon Classed A 1

REPAIRS

an order for Survey on this Vessel for the purpose of ascertaining her way & Condition was left at this office on Saturday the 22nd and on visiting her this morning we found the water flowing into the dock so that the bottom below the bilge could not be seen and the Owner stated that he declined having her surveyed as he did not intend repairing her but intended to sell her. We observed that the Mizen Mast was decayed and pointed it out to the Owner & Master.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Under these Circumstances we are of opinion her Character should be suspended until she is submitted

The Amount of Fee..... is received by me,

Special.....

Certificate (if required) :

Committee's Minute

Character assigned

Charge £ 1. 1

25th June 1850

Examine Character

Charge £ 1. 1

25th June

LON 628 0405

© 2019 Lloyd's Register Foundation