

REPORT of SURVEY for REPAIRS.

16125

No. ⁶⁴⁷ Survey held at London Date 22nd June 1850
 on the B^{re} "Constance" Master J B Godfrey
 Tonnage 578 Built at Sunderland When built 1848
 By whom built _____ Owners J Marshall
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock in King & Queen

Last Survey, No. 14242 Port London Classed 10 A 1

REPAIRS

at present 7 pairs of Knee Udders fitted to the hold beams thro' bolted with yellow metal also two pairs iron hanging knees fitted to the upper deck beams aft - bottom strapped Caulked, and Sheathed with yellow metal on paper rudder bands thro' fastened

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>four</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>and</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>21</u> <u>sufficient</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>yes</u> When put on <u>June</u> 18 <u>50</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This Vessel is in efficient Condition and fit to remain at Chapel

The Amount of Fee.....£ : : is received by me, J H Ritchie

Special..... : :

Certificate (if required) : :

Committee's Minute 9th July 1850

Character assigned 10 A 1 Good



© 2019

Lloyd's Register Foundation

LON 628 - 0 433