

REPORT of SURVEY for REPAIRS.

10310

No. 257 Survey held at London Date 15th 23rd Aug 1850
 on the B^{re} "Bolton" Master Young
 Tonnage 541 Built at Liverpool When built 1822
 By whom built _____ Owners Ingram
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Messrs Weymans Dock

Last Survey, No. 15284 Port London Classed * A, 1
SS 1849

REPAIRS

at present the four upper Courses of Yellow Metal stripped and the uncovered seams Caulked and yellow Metal replaced on felt - One new Gentie fitted to the Budder & new after Piece of false Rail fitted yellow Metal & repaired - Ceiling in hold & new and repaired - two new Middle Piece beams fitted to take the Machinery a new Counter Transom fitted & secured with Iron Pins at each end -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

Good

Good

Good and Sufficient

General Observations and Opinion,

This Vessel appears in efficient Condition and fit for the safe Conveyance of dry and perishable Cargoes to & from all Ports of the World and may remain Clipped

The Amount of Fee..... is received by me, W. A. W. A. W.
 Special.....
 Certificate (if required)

Committee's Minute 1st Oct 18 50
 Character assigned 1st 1st 1st
 Special £ 1 -