

REPORT of SURVEY for REPAIRS. & Change of Property

16342

No. 118 Survey held at London Date October 4 1850
 on the Bk New Express Master Alex. Mc Bride
 Tonnage 277 Built at Pole When built 1830
 By whom built _____ Owners Mc Bride & Co
 Port belonging to London Destined Voyage Trinidad
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 13908 Port London Cont 50 — 4 Classed 12 A 1

REPAIRS In 1840 caulked & sheathed with yellow metal

Present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>Do</u>	Breasthooks and Stemson <u>Do</u>	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good wherever</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers _____	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower Stn & 2 Kedge</u>
Sheerstrakes _____	Ceiling <u>Do</u>	Cables <u>well found</u>
Topsides _____	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales _____	Copper _____ When put on <u>1840</u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter _____		

General Observations and Opinion, Is in a very good & efficient state to retain her present class

The Amount of Fee.....£ 1 : — : — is received by me, A. Whitton

Special.....: : —

Certificate (if required) : : —

Committee's Minute 15th Oct^r 1850.

Character assigned Cont 4 to 1

record Ym L D



© 2019

Lloyd's Register
Foundation

LON 629 - 0192