

REPORT of SURVEY for REPAIRS.

Classification

No. 1 Survey held at London Date 11th & 22nd Jan^y 1850
 on the Brig "Albert" Master H Marmand
 Tonnage 229 Built at Cape Breton When built 1849
 By whom built _____ Owners H Marmand
 Port belonging to Orichat Destined Voyage _____
 If Surveyed Afloat or in Dry Dock on Wests Slip

Dec 29 1850

Length 90 ft Breadth 24 ft Depth 13 ft 8 in

Survey, No. None Port Not Classed

IRS

The Master requested this Vessel might be surveyed for Classification and on my examining her for that purpose I found she required three additional hold beams and a pair of Pointers to the Stern frame and to be opened at the bilges according to the Sect. 62 but the Master (who is also Owner) declined doing so on account of the expense — under these Circumstances I cannot recommend her for Classification

J. H. Hatcher

Special L.P. 1 — paid

Condition of the

Treenails

Windlass and Capstan

Breasthooks and Stemson

Pumps

Transoms, Pointers, and Crutches

Boats

Timbers of the Frame

Masts, Yards, &c.

Keelsons

Sails

Clamps and Shelves

Anchors No. of

Ceiling

Cables

Rudder

Hawsers and Warps

Copper

When put on

Standing & Running Rigging

General Observations and Opinion,

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : — paid

Certificate (if required) : :

Committee's Minute _____ 18____

Character assigned _____

Robt. Brookway
Agent



© 2019

Lloyd's Register
 Foundation

LVG29-0232