

REPORT of SURVEY for REPAIRS.

16421

No. 7 Survey held at Sondou Date 2^o 48th Nov. 1850
 On the B^{re} Waterken Master W^m Dodds
 Tonnage 355 Built at Kull When built 1825
 By whom built _____ Owners Robertson
 Port belonging to Sondou Destined Voyage Matta
 If Surveyed Afloat or in Dry Dock in Mess^r Fletchers Dock

Last Survey, No. 13841 Port Sondou Classed A1

REPAIRS at present new false Kull fitted hung in shores
bottom sheathed with Zinc - topsides and waterways
Caulked - Rudder bands refastened

Present Condition of the

Decks <u>Partly Caulked</u>	Treenails _____	Windlass and Capstan <u>Good</u>
Waterways <u>Caulked</u>	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>Three</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>Suff^{ce}</u>
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails <u>2 Sails</u>
Planksheers <u>Good</u>	Clamp and Shelves _____	Anchors No. of <u>3 1 1</u>
Sheerstrakes <u>Caulked</u>	Ceiling _____	Cables <u>Sufficient</u>
Topsides <u>Caulked</u>	Rudder _____	Hawsers and Warps <u>Do</u>
Wales _____	Copper <u>Zinc</u> When put on <u>Nov 1850</u>	Standing & Running Rigging <u>Do</u>
Plank (Bottom) and Counter _____		

General Observations and Opinion,

This Vessel appears in efficient
Condition & fit for the safe conveyance
of dry perishable Cargoes and

The Amount of Fee.....£ : : is received by me Wm. Hemmings

Special..... : :

Certificate (if required) : :

Committee's Minute 15th Nov^r 18 50

Character assigned A1



© 2019

Lloyd's Register
Foundation

LCN 629-0280