

ANNUAL SURVEYS.

10513

No. 623 Survey held at London Date Dec 30 1850
 on the Bk. Mately Master Ginder
 Tonnage 400 Built at Sunderland When built 1847
 By whom built _____ Owners Fletcher
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Mathew Dock

Recd Aug 1851

Last Survey, No. 14049 Port of London 1040 Classed 10 A1

Present Condition of the

ways <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>good</u>
gs <u>Do</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>Do</u>
Deck Beams & Fastenings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Deck Beams & Fastenings <u>Do</u>	Timbers of the Frame <u>good & sound</u>	Masts, Yards, &c. <u>Do</u>
sheers <u>Good</u>	Keelsons <u>good</u>	Sails <u>well found</u>
trakes <u>Good</u>	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower Stm & 2 Hedge</u>
les <u>Good</u>	Ceiling <u>Do</u>	Cables <u>well found</u>
	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
(Bottom) and Counter <u>Copper 1/4 m</u>	When put on <u>Dec 1850</u>	Standing & Running Rigging <u>good</u>

Observations and Opinion. Has been in dry dock, bottom stripped, caulked and sheathed with yellow metal, upon her good & efficient condition am of opinion she may retain her present character

Committee Minute 3rd Jan 1851

Inspector assigned 10 A1

R. Middleton

Certificate (if required)

No. 184 Survey held at London Date Dec 30 & 31 1850
 on the Bk. Sarah Metcalfe Master Yostin
 Tonnage 455 Built at Jarrow When built 1840
 By whom built _____ Owners Metcalfe
 Port belonging to N. Shields Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock St Mathew Dock

Last Survey, No. 4000 Port of Newcastle Classed PA1

Present Condition of the

ays <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>good</u>
<u>Do</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>Do</u>
<u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Deck Beams & Fastenings <u>Do</u>	Timbers of the Frame <u>good & sound</u>	Masts, Yards, &c. <u>Do</u>
Deck Beams & Fastenings <u>Do</u>	Keelsons <u>good</u>	Sails <u>well found</u>
eeers <u>Good</u>	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower Stm 2 Hedge</u>
akes <u>Good</u>	Ceiling <u>Do</u>	Cables <u>well found</u>
	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
(Bottom) and Counter <u>Copper 1/4 m</u>	When put on <u>1840</u>	Standing & Running Rigging <u>good</u>

Observations and Opinion. This vessel appears in all respects in a good & efficient state to continue as classed

Committee Minute 3rd Jan 1851

Inspector assigned 10 A1

R. Middleton

© 2019



Lloyd's Register Foundation

Certificate (if required)

LON 629-0370