

REPORT of SURVEY for REPAIRS.

10514

No. 376 Survey held at London Date January 3 1857
 on the SS Mary Master Harvey
 Tonnage 80 Built at Sunderland When built 1842
 By whom built 67 Owners C Harvey
 Port belonging to Towry Destined Voyage Switzerland
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 893 Port Duport Classed F. 1

REPAIRS At Lowestoffe in June from collision on the starboard side
new Sheersake, three new planks in the sides 7 new bftimber
on the Port side 26 feet of sheersake, 4 lodging knees,
bottom & bldges rebitted, 14 new sections and caulked
from the keel to the gunwale & the decks

Present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>Do</u>	Breasthooks and Stemson <u>Do</u>	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>good</u>	Sails <u>Do</u>
Planksheers <u>Good</u>	Clump and Shelves <u>Do</u>	Anchors No. of <u>sufficient</u>
Sheerstrakes <u>Do</u>	Ceiling <u>Do</u>	Cables <u>Do</u>
Topsides <u>Do</u>	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales <u>Do</u>	Copper <u>Do</u>	Standing & Running Rigging <u>Do</u>
Plank (Bottom) and Counter <u>good</u>	When put on <u>Do</u>	

General Observations and Opinion, I am of opinion this vessel is in a good & efficient
state for the safe conveyance of dry & perishable
cargoes & may continue as classed F. 1


The Amount of Fee.....£ — : 10 : — is received by me,

Special.....

Certificate (if required) : 5 : —

Committee's Minute 7th Jan'y 1857

Character assigned AL Edward Davis



© 2019

Lloyd's Register
Foundation

LCNG29-0371