

REPORT of SURVEY for REPAIRS.

16541

No. Survey held at London Date 7th Dec^r 1850
 on the Ship "Samarang" Master Esott
 Tonnage 481 Built at London When built 1840
 By whom built Owners M. Wigram
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock in Messrs Wigram's Dock

Dec 15 1851

Last Survey, No. 12301 Port London Classed 12 A 1

REPAIRS at present from being wormed new four pieces of
 Keel of English Elm & new lower pieces of them and
 outer stem part new false Keel one piece new
 Keelson of East India Teak under four masts
 bottom stripped Caulked from the Keel up to the
 gunwales and bottom sheathed with Yellow Pine
 Hull & spars rigging generally overhauled & refitted

Mem^o. The owner does not wish
 these repairs to be entered in the
 Register Books. JH 18/1/51

ent Condition of the

ks	Treenails	Windlass and Capstan
erways	Breasthooks and Stenson	Pumps
ings	Transoms, Pointers, and Crutches	Boats
er Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
er Deck Beams & Fastenings	Keelsons	Sails
nk-sheers	Clamps and Shelves	Anchors No. of
erstrakes	Ceiling	Cables
sides	Rudder	Hawsers and Warps
es	Copper <u>ym</u> When put on <u>Dec^r 1850</u>	Standing & Running Rigging

ral Observations and Opinion,

This vessel is in efficient Condition
 and fit to remain as classed

Amount of Fee.....£ 2 : - : - is received by me, JH Ritchie

Special.....

Certificate (if required)

Committee's Minute 21st Jan^y 1851

Character assigned 12 A 1
James L. x J.H.R. L.H.



© 2019
 Lloyd's Register
 Foundation
 LON 629 - 0398